

# **Asbestos Containing Materials Inspection**

**Capital Plaza Office Tower  
500 Mero Street  
Frankfort, Kentucky**



Prepared for:

**Kentucky Finance & Administration Cabinet  
Division of Engineering & Contract Administration  
403 Wapping Street  
Frankfort, Kentucky 40601**

Prepared by:

**Lee Engineering, LLC  
Environment & Infrastructure**

**P.O. Box 500  
Lawrenceburg, KY 40342  
(502) 859-0190 ♦ (502) 859-3000 fax  
jlleeeng@bellsouth.net**

*April 7, 2014*

April 7, 2014

Mr. Maziar Torabi  
KY Finance and Administration Cabinet  
Division of Engineering  
Frankfort, KY 40601

RE: Asbestos Inspection  
Capital Plaza Office Tower  
500 Mero Street  
Frankfort, KY 40601

Dear Mr. Torabi:

Lee Engineering, LLC has completed the authorized asbestos inspection of the Capital Plaza Office Tower located at 500 Mero Street, Frankfort, Kentucky. Several visits to the site were made in 2014: February 25, February 27, March 6 and March 26. Figure 1 shows the location of the building located at 500 Mero Street, Frankfort, Kentucky.

The objective of the inspection was to identify asbestos containing materials (ACM) that could be potentially disturbed by maintenance workers. Generally, the building has defined work areas, offices, hallways/stairwells, maintenance/heating/cooling areas and other service areas (bathrooms, electric and communications rooms).

Asbestos containing materials (ACM) were present in several areas. ACM's were found in the following locations/floors: Ground Floor, Crawl Space, Floor 13A, 13B, Floor 15. Starting at the Ground Floor, ACM's were found to be present in the Fan Room, Storage Room, Boiler Room and the Mechanical Room. There are two entry points to the Crawl Space from either stair well between the first and second floor. Two of the samples tested positive for ACM; sample # 139 and #141. In our report, we have tried to put in chronological order, the sample results, floor plans, pictures and COC's to show the location of all ACM's. With the exception of materials associated with mechanical chases, the only sample testing positive was on the 15th floor. Analytical results for each floor are highlighted in yellow; however samples that contain ACM are highlighted in light blue. Samples are located on floor plans in red with the exception of floor 13A in which samples are labeled in the color of the corresponding pipe. It should be assumed that all fire doors have friable asbestos cores.

P.O. Box 500  
Lawrenceburg, Kentucky 40342  
Ph: (502) 859-0190  
Fx: (502) 859-3000  
jlleeng@bellsouth.net  
Lee Engineering, LLC  
Environment & Infrastructure

On every office floor, there was 12 inch floor tile that appeared to be the same material. There were some patch areas that had different colors of 12 inch tile, but all tested negative for asbestos. A summary of the sampling locations and analytical results for the positive samples are included in the table below.

**Table 1 – Asbestos Containing Materials Inspection Summary**

<b>Sample ID</b>	<b>Location</b>	<b>Matrix</b>	<b>Color</b>	<b>Asbestos Content, %</b>
58	Ground floor – Fan Room	Pipe wrap insulation	White	5
60	Ground floor – Fan Room	Elbow insulation	White	10
62	Ground floor – Fan Room	Pipe wrap insulation	White	5
66	Ground floor – Storage Room	Elbow insulation	White	7
67	Ground floor-Storage Room	Elbow insulation	White	5
78	Ground floor-Boiler Room	Over pack insulation	White	12
79	Ground floor-Mechanical Room	Valve junction	Yellow	15
81	Ground floor-Mechanical Room	Valve wrap insulation	White	3
139	Crawl Space – Between 1 <sup>st</sup> and 2 <sup>nd</sup> floor	Pipe -Fitting coating	White	5
141	Crawl Space – Between 1 <sup>st</sup> and 2 <sup>nd</sup> floor	Pipe -Fitting/elbow coating	White	15
24	Floor 13A-loose laying on top of unit	Pipe wrap insulation		35
28	Floor 13A	Elbow insulation	White	5
31	Floor 13A	Pipe wrap insulation	White	12
32	Floor 13A	Valve insulation	White	20
36	Floor 13A	Elbow insulation	White	15
37	Floor 13A	Elbow insulation	White	12
38	Floor 13A	Elbow insulation	White	12
44	Floor 13A	Pipe wrap insulation	White	10
45	Floor 13A	Pipe wrap insulation	White	8
51	Floor 13B	Pipe wrap insulation	White	15
52	Floor 13B	Pipe wrap insulation	White	12
53	Floor 13B	Valve insulation	White	12
1	Under 14 <sup>th</sup> floor	Pipe insulation	White	45
121M	Floor 15 – mastic	Floor tile mastic	Black	2

It is our opinion that based on the inspection and the analytical results the main areas of concern are the ground floor, floor 13A, floor 13B. the crawl space"cpf "mqqt"36. Please call me at (502) 600-0016 if you have any questions.


Sincerely,

Jeff Lee, P.E.

P.O. Box 500  
Lawrenceburg, Kentucky 40342  
Ph: (502) 859-0190  
Fx: (502) 859-3000  
[jilleeng@bellsouth.net](mailto:jilleeng@bellsouth.net)



<b>F&amp;A Division of Engineering</b> <b>403 Wapping Street 1stFloor</b> <b>Frankfort, Kentucky 40601</b>	<b>FIGURE 1</b>
<a href="#">Lee Engineering, LLC</a> P.O. Box 500 Lawrenceburg, KY 40342	Capital Plaza Office Tower 500 Mero Street Frankfort, Kentucky 40601



SEE ENLARGED PLAN SH. A-38

SEE ENLARGED PLAN SH. A-38

Ground Floor  
Capital Plaza Office Tower

95

94

97

58

57

56

62

59

61

60

67

68

63

64

65

66

93

91

90

92

89

87

88

Ceramic

Ceramic

SER. DIV. STORAGE  
G18

TRASH ROOM  
G19

RECEIVING  
G20

CORRIDOR  
G17

MAINTENANCE  
G21

SHOWER ROOM  
G24

PARTS STORAGE  
G33

FAN ROOM  
G32

STAIRS 1  
G15

SHAFT A  
G13

ELEVATOR LOBBY  
G12

GALLERY  
G24

SHAFT B  
G23

MEETING ROOM  
G22

AUDITORIUM  
G14

SHAFT D  
G11

GALLERY  
G10

LOBBY  
G09

SHAFT C  
G25

MEETING ROOM  
G26

STAIRS 2  
G28

KITCHEN  
G04

CHAIRS  
G05

POWDER ROOM  
G08

VESTIBULE  
G29

MEN  
G30

SER. DIV. STORAGE  
G27

PANTRY  
G03

CHASE  
G06

WOMEN  
G07

JANITOR  
G02

ARRIVAL LOBBY  
G01

TERRAZZO PATTERN SYMMETRICAL ABOUT E

DEPART


WORKING PT. B

A  
A-42

D  
A-42


C  
A-42

E  
A-42



Ground Floor  
Capital Plaza Office Tower

Ground Floor  
Capital Plaza Office Tower



494.00  
494.50

494.00  
494.50

494.00  
494.50

WATER METER VAULT

SERVICE AREA

X-38

PIPE TUNNEL 8'-0" W x 6'-0" HGT. (CLEAR INSIDE) TOP TUNNEL SLAB @ EL. 494.01'

ELECTRICAL EQUIP AREA

NOTE: MECH. & ELECT. EQUIP. PADS AND PIERCE SIZE LOCATION & HGT. TO BE VERIFIED WITH MECH. CONTRACTOR

PIT COVER OF 1/4" THICK CHECKERED STEEL PL

MECH. RM. X-26  
FL. EL. 496.01'

LOADING DOCK

CORRIDOR X-25

EXHAUST FANS SEE MECHANICAL DWGS. AND SPECS.

LOADING PLATFORM X-18

RELOCATE DOOR X-50 AS SHOWN DOOR & FRAME SHALL REMAIN AS SH.

CHANGE DOOR X-51 TO A PAIR OF 2'-8" x 7'-10" x 1 3/4" STEEL DOORS WITH H.M. FRAME HARDWARE AS FOLLOWS: LOCKSET # 7599 4 PAIRS OF BUTTS, 1 CLOSER 1 TOP & BOTTOM FLUSH BOLTS, 2 FLOOR MOUNTED DOOR HOLDERS & BLUMPER'S CAST BRONZE EQUAL TO GLYNN-JOHNSON # 61020, 2 ARMOR PLATES 2'-6" x 3'-4" OIL RUBBER BRONZE INSIDE FACES ONLY. MOUNT LOCKSET & CLOSER ON ACTIVE LEAF MOUNT FLUSH BOLTS IN ACTIVE LEAF

PAINT SHOP X-19

CARPENTRY SHOP X-20

RECEIVING RM. X-21

MAIL RM X-22

SEE GLEV D & E FOR DETAIL MILLWORK

CONTROL RM X-23  
FL. EL. 498.01'

BOILER RM. X-24  
FL. EL. 496.01'

BOILER CURBS

SERVICE SINK

INTEL-L4

1-4" I.D. PIPE RAIL SET IN 6" DEEP PIPE GLEEVE & LEAD IN

4" HIGH EQUIP. PADS

22x24" COL.

22x24" COL.

22x24" COL.

86

81

82

79

80

85

84

83

77

78

76

75

74

73

96

54

55

70

69

71


72



Sample 54  
Floor tile  
Ground floor



Sample 55  
Ceiling tile  
Ground floor



Sample 56  
Vent tape  
Ground floor



Sample 57  
Pipe wrap  
Ground floor



Sample 58  
Pipe wrap  
Ground floor



Sample 59  
Pipe wrap  
Ground floor



Sample 60  
Elbow  
Ground floor



Sample 61  
Pipe wrap  
Ground floor



Sample 62  
Pipe wrap  
Ground floor



Sample 63  
Vent tape  
Ground floor



Sample 64  
Tape mud  
Ground floor




Sample 65  
Pipe wrap  
Ground floor



Sample 66  
Elbow  
Ground floor



Sample 67  
Elbow  
Ground floor



Sample 68  
Pipe wrap  
Ground floor



Sample 69  
Pipe wrap  
Boiler Room



Sample 70  
Elbow  
Boiler Room



Sample 71  
Pipe wrap  
Boiler Room




Sample 72  
Elbow  
Boiler Room



Sample 73  
Tank insulation  
Boiler Room



Sample 74  
Pipe wrap tank  
Boiler Room



Sample 75  
Door insulation  
Boiler Room



Sample 76  
Pipe wrap tank  
Boiler Room



Sample 77  
Pipe wrap  
Boiler Room



Sample 78  
Over pack  
Boiler Room



Sample 79  
Valve junction  
Mechanical Room



Sample 80  
Pipe insulation  
Mechanical Room



Sample 81  
Valve wrap  
Mechanical Room



Sample 82  
Elbow  
Mechanical Room



Sample 83  
Pipe insulation  
Mechanical Room



Sample 84  
Elbow  
Mechanical Room



Sample 85  
Loose thermal  
Mechanical Room




Sample 86  
Ceiling tile  
Ground floor



Sample 87  
Ceiling tile  
Ground floor



Sample 88  
Pipe wrap  
Ground floor



Sample 89  
Baseboard mastic  
Ground floor



Sample 90  
Floor tile  
Ground floor



Sample 91  
Floor tile  
Ground floor



Sample 92  
Ceiling tile  
Ground floor



Sample 93  
Wall covering  
Ground floor



Sample 94  
Ceiling tile  
Ground floor



Sample 95  
Ceiling tile  
Ground floor



Sample 96  
Floor tile  
Ground floor



Sample 97  
Ceiling covering  
Ground floor

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 50	Yellow	Yes	Yes				None		98%		2%
# 51	White	Yes	Yes	15%				3%	37%		45%
# 52	White	Yes	Yes	12%				3%	40%		45%
# 53	White	Yes	Yes	12%				2%	38%		48%
# 54	Yellow	Yes	Yes				None	2%			98%
# 55	White	Yes	Yes				None	55%	30%		15%
# 56	White	Yes	Yes				None	98%			2%
# 57	Yellow	Yes	Yes				None		99%		1%
# 58	White	Yes	Yes	5%				3%	42%		50%
# 59	Yellow	Yes	Yes				None		98%		2%
# 60	White	Yes	Yes	10%				3%	52%		35%
# 61	Yellow	Yes	Yes				None		98%		2%
# 62	White	Yes	Yes	5%				2%	43%		50%
# 63	White	Yes	Yes				None	55%	40%		5%
# 64	White	Yes	Yes				None	5%			95%
# 65	Yellow	Yes	Yes				None		97%		3%
# 66	White	Yes	Yes	7%				3%	25%		65%
# 67	White	Yes	Yes	5%				2%	40%		55%
# 68	Yellow	Yes	Yes				None		99%		1%
# 69	Yellow	Yes	Yes				None		97%		3%

Methodology : EPA Method 600/R-93-116

Page # 3

Date Analyzed : 5-Mar-14  
 Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_



The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 70	Pink	Yes	Yes				None		99%		1%
# 71	Yellow	Yes	Yes				None		97%		3%
# 72	Yellow	Yes	Yes				None		99%		1%
# 73	Mixed	Yes	Yes				None	5%	93%		2%
# 74	Yellow	Yes	Yes				None		98%		2%
# 75	White	Yes	Yes				None		97%		3%
# 76	Yellow	Yes	Yes				None		99%		1%
# 77	Yellow	Yes	Yes				None		99%		1%
# 78	White	Yes	Yes	12%				3%	50%		35%
# 79	White	Yes	Yes	15%				5%	45%		35%
# 80	Yellow	Yes	Yes				None		99%		1%
# 81	White	Yes	Yes	3%				5%			92%
# 82	Yellow	Yes	Yes				None		97%		3%
# 83	Yellow	Yes	Yes				None		99%		1%
# 84	Yellow	Yes	Yes				None		98%		2%
# 85	White	Yes	Yes				None	43%			57%
# 86	White	Yes	Yes				None	55%	30%		15%
# 87	White	Yes	Yes				None	58%	27%		15%
# 88	Yellow	Yes	Yes				None		98%		2%
# 89	Yellow	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 4

Date Analyzed : 7-Mar-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
 Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 90	Tan	Yes	Yes				None	3%			97%
# 91	White	Yes	Yes				None	2%			98%
# 92	White	Yes	Yes				None	55%	30%		15%
# 93	White	Yes	Yes				None	12%			88%
# 94	White	Yes	Yes				None	58%	27%		15%
# 95	White	Yes	Yes				None	55%	25%		20%
# 96	White	Yes	Yes				None	2%			98%
# 97	White	Yes	Yes				None	8%			92%
# 98	White	Yes	Yes				None	3%			97%
# 99	Gray	Yes	Yes				None				100%
# 100	Green	Yes	Yes				None	2%			98%
# 101	Black	Yes	No				None				100%
# 102	White	Yes	Yes				None	2%			98%
# 103	White	Yes	Yes				None	3%			97%
# 104	White	Yes	Yes				None	2%			98%
# 105	White	Yes	Yes				None	3%			97%

Methodology : EPA Method 600/R-93-116

Page # 5

Date Analyzed : 14-Mar-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>2-27-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc  P.O. Box 500  Lawrenceburg, KY 40341  Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	color of pipe Comments
54	Control room	G	floor	tile	gray		
55	Control room	G	ceiling	tile	white		
56	Fan Room	G	vent tape	tape	white	18"	
57	Fan Room	G	pipe wrap	insulation		8"	green
58	Fan Room	G	pipe wrap	insulation	white	10"	orange
59	Fan Room	G	pipe wrap	insulation	yellow	6"	orange
60	Fan Room	G	elbow	insulation	white	4"	green
61	Fan Room	G	pipe wrap	insulation	yellow	4"	green
62	Fan Room	G	pipe wrap	insulation	white	6"	orange
63	Storage room	G	vent tape	tape	white	30"	white
64	Storage room	G	tape mud	mud	white	30"	white
65	Storage room	G	pipe wrap	insulation	yellow	10"	green
66	Storage room	G	elbow	insulation	white	10"	green
67	Storage room	G	elbow	insulation	white	3"	green
68	Storage room	G	pipe wrap	insulation	yellow	3"	green
69	Boiler Room	G	pipe wrap	insulation	yellow	20"	white
70	Boiler Room	G	elbow	insulation	pink	20"	orange
71	Boiler Room	G	pipe wrap	insulation	yellow	10"	orange
72	Boiler Room	G	elbow	insulation	yellow	10"	orange
73	Boiler Room	G	tank insulation	insulation	white/yellow	500gal	white
Relinquished By: Signature			Received By: Signature			Date & Time	
Relinquished By: Signature			Received By: Signature			Date & Time	

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>2-27-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc  P.O. Box 500 Lawrenceburg, KY 40341  Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	color of pipe Comments
74	Boiler	G	pipe wrap tank	insulation	yellow	4"	white
75	Boiler	G	door insulation	insulation on tank	white	500 gal	light green
76	Boiler	G	pipe wrap tank	insulation	yellow	500 gal	silver
77	Boiler	G	pipe wrap	insulation	yellow	4"	light blue
78	Boiler	G	over pack	insulation	white	24"	gray
79	Mechan.	G	valve junction	insulation	yellow	18"	green
80	Mech.	G	pipe insul.	insulation	yellow	18"	green
81	Mech.	G	valve wrap	insulation	white	24"	green
82	Mech.	G	elbow	insulation	yellow	18"	green
83	Mech.	G	pipe insul.	insulation	yellow	18"	orange
84	Mech.	G	elbow	plastic coated	yellow	18"	orange
85	Mech.	G	loose thermal	insulation	white	3"	white-loose
86	Receiving + Supply	G	ceiling	tile	white		
87	Janitor room	G	ceiling	tile	white		
88	Janitor room	G	pipe wrap	insulation	yellow	6"	white
89	Meeting room	G	baseboard	mastic	yellow		gray
90	Kitchen	G	floor	tile	tan		
91	Audit.	G	floor	tile	gray		
92	Kitchen	G	ceiling	tile	white		
93	Audit.	G	wall	covering	white		gray marble



Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time

**Asbestos Inspection Form and Chain of Custody**

Project: <u>Capital Plaza Office Tower</u> Date: <u>2-27-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------


Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
94	trash room	G	ceiling	tile	white	2'x4'	
95	receiving	G	ceiling	tile	white	2'x2'	
96	carpentry	G	floor	tile	white	12'x12'	
97	shower room	G	ceiling	covering	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



PLAN 1ST THRU 11TH FLOORS SECTOR C-2

1/8" = 1'-0"



Sample 98  
Ceiling plaster  
Floor 1



Sample 99A  
Sample 99B  
Floor concrete/mastic  
Floor 1



Sample 100  
Floor tile - 12 inch  
Floor 1



Sample 101  
Water unit insulation  
Floor 1

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

Number	Color			% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
		Layered	Fibrous	Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 90	Tan	Yes	Yes				None	3%			97%
# 91	White	Yes	Yes				None	2%			98%
# 92	White	Yes	Yes				None	55%	30%		15%
# 93	White	Yes	Yes				None	12%			88%
# 94	White	Yes	Yes				None	58%	27%		15%
# 95	White	Yes	Yes				None	55%	25%		20%
# 96	White	Yes	Yes				None	2%			98%
# 97	White	Yes	Yes				None	8%			92%
# 98	White	Yes	Yes				None	3%			97%
# 99	Gray	Yes	Yes				None				100%
# 100	Green	Yes	Yes				None	2%			98%
# 101	Black	Yes	No				None				100%
# 102	White	Yes	Yes				None	2%			98%
# 103	White	Yes	Yes				None	3%			97%
# 104	White	Yes	Yes				None	2%			98%
# 105	White	Yes	Yes				None	3%			97%

Methodology : EPA Method 600/R-93-116

Page # 5

Date Analyzed : 14-Mar-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.


AIHA # 102459

AJHA #1 02459

## Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u>	Lee Engineering, llc
Date: <u>3-6-14</u>	P.O. Box 500
Address: <u>500 Mero Street, Frankfort</u>	Lawrenceburg, KY 40341
Sampled By: <u>Bob Keiser</u>	Ph (502)600-0016

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
98	Mens Restroom	1	ceiling	tile	white		
99A	105	1	floor	concrete	gray		
99B	105	1	floor	mastic	gray		
100	125B	1	floor	tile	green	12"	
101	125B	1	HVAC water unit	insulation	black		
102	near 210	2	floor	tile	white	12"	
103	319	3	floor	tile	white	12"	
104	429	4	floor	tile	white	12"	
105	507	5	floor	tile	white	12"	
Relinquished By: Signature			Received By: Signature		Date & Time		
Relinquished By: Signature			Received By: Signature		Date & Time		



Crawl Space  
Between First and Second Floor



Sample 135  
Pipe wrapping  
Crawl Space



Sample 136  
Piping insulation  
Crawl Space



Sample 137  
Elbow  
Crawl Space

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 125	White	Yes	Yes				None	8%			92%
# 126	White	Yes	Yes				None	5%			95%
# 127	White	Yes	Yes				None	3%			97%
# 128 T	White	Yes	Yes				None	3%			97%
# 128 M	Tan	Yes	No				None	2%			98%
# 129	White	Yes	Yes				None	4%			96%
# 130	White	Yes	Yes				None	45%	30%		25%
# 131 T	White	Yes	Yes				None	2%			98%
# 131 M	Tan	Yes	No				None	3%			97%
# 132 T	White	Yes	Yes				None	3%			97%
# 132 M	Tan	Yes	No				None	2%			98%
# 133	White	Yes	Yes				None	5%			95%
# 134 T	White	Yes	Yes				None	3%			97%
# 134 M	Tan	Yes	No				None	3%			97%
# 135	White	Yes	Yes				None	10%	25%		65%
# 136	Yellow	Yes	Yes				None		99%		1%
# 137	White	Yes	Yes	< 1%				2%	10%		88%

Methodology : EPA Method 600/R-93-116

Page # 7

Date Analyzed : 11-Apr-14  
Analyst : Winterford MensahReviewed By: 

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis # 2105104 Address: 500 Mero Street, Frankfort, KY  
Client Name: State Of Kentucky (Capital Plaza Office Tower)  
Sampled By: Bob Keiser  
A = Tape / B = Insulation

				% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
Number	Color	Layered	Fibrous	Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 138	Yellow	Yes	Yes				None		99%		1%
# 139	White	Yes	Yes	5%				3%			92%
# 140 A	White	Yes	Yes				None	5%	30%		65%
# 140 B	Yellow	Yes	Yes						97%		3%
# 141	White	Yes	Yes	15%				5%			80%

Methodology : EPA Method 600/R-93-116  
Date Analyzed : 10-May-14  
Analyst : Winterford Mensah

Reviewed By:   
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

**Asbestos Inspection Form and Chain of Custody**

Project: <u>Capital Plaza Office Tower</u>	<b>Lee Engineering, llc</b> P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
Date: <u>3-26-14</u>	
Address: <u>500 Mero Street, Frankfort</u>	
Sampled By: <u>Bob Keiser</u>	

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
126	1109	11	floor	tile	white		
127	near 1019	10	floor	tile	white		
128	near 922	9	floor	tile	white		
129	Lobby	9	ceiling	texture	white		
130	Mens RR	8	ceiling	tile	white		
131	821	8	floor	tile	white		
132	705	7	floor	tile	white		
133	Lobby	6	ceiling	texture	white		
134	614	6	floor	tile	white		
135	starwell	L/1	pipe wrapping	white wrapping	white		
136	starwell	L/1	pipe	insul	yellow		
137	starwell	L/1	elbow	plaster	gray		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time

### Asbestos Inspection Form and Chain of Custody


<b>Project</b>	Capital Plaza Office Tower	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
<b>Date</b>	04/25/14	
<b>Address</b>	500 Mero Street, Frankfort, KY	
<b>Sampled By</b>	Bob Keiser	

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
138	Stairwell	L/1	Run	Insulation	Yellow		
139	Stairwell	L/1	Fitting	Coating	White		
140	Stairwell	L/1	Big pipe	Tape/insulation			
141	Stairwell	L/1	Fitting/elbow	Coating	white		

Relinquished By: Signature	Received By: Signature <i>[Handwritten Signature]</i>	Date & Time <i>4/28/14</i>
Relinquished By: Signature	Received By: Signature	Date & Time



102



PLAN 1ST THRU 11TH FLOORS SECTOR C-2

1/8" = 1'-0"



Sample 102  
Floor tile - 12 inch  
Floor 2

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

Number	Color	% FIBROUS ASBESTOS						% NON-ASBESTOS FIBERS			
		Layered	Fibrous	Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 90	Tan	Yes	Yes				None	3%			97%
# 91	White	Yes	Yes				None	2%			98%
# 92	White	Yes	Yes				None	55%	30%		15%
# 93	White	Yes	Yes				None	12%			88%
# 94	White	Yes	Yes				None	58%	27%		15%
# 95	White	Yes	Yes				None	55%	25%		20%
# 96	White	Yes	Yes				None	2%			98%
# 97	White	Yes	Yes				None	8%			92%
# 98	White	Yes	Yes				None	3%			97%
# 99	Gray	Yes	Yes				None				100%
# 100	Green	Yes	Yes				None	2%			98%
# 101	Black	Yes	No				None				100%
# 102	White	Yes	Yes				None	2%			98%
# 103	White	Yes	Yes				None	3%			97%
# 104	White	Yes	Yes				None	2%			98%
# 105	White	Yes	Yes				None	3%			97%

Methodology : EPA Method 600/R-93-116

Page # 5

Date Analyzed : 14-Mar-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459



AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>3-6-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
--------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------


Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
98	Mens Restroom	1	ceiling	tile	white		
99A	105	1	floor	concrete	gray		
99B	105	1	floor	mastic	gray		
100	125B	1	floor	tile	green	12"	
101	125B	1	HVAC water unit	insulation	black		
102	near 210	2	floor	tile	white	12"	
103	319	3	floor	tile	white	12"	
104	429	4	floor	tile	white	12"	
105	507	5	floor	tile	white	12"	

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



PLAN 1ST THRU 11TH FLOORS SECTOR C-2

1/8" = 1'-0"



Sample 103  
Floor tile- 12 inch  
Floor 3

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

Number	Color	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS					
		Layered	Fibrous	Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 90	Tan	Yes	Yes				None	3%			97%
# 91	White	Yes	Yes				None	2%			98%
# 92	White	Yes	Yes				None	55%	30%		15%
# 93	White	Yes	Yes				None	12%			88%
# 94	White	Yes	Yes				None	58%	27%		15%
# 95	White	Yes	Yes				None	55%	25%		20%
# 96	White	Yes	Yes				None	2%			98%
# 97	White	Yes	Yes				None	8%			92%
# 98	White	Yes	Yes				None	3%			97%
# 99	Gray	Yes	Yes				None				100%
# 100	Green	Yes	Yes				None	2%			98%
# 101	Black	Yes	No				None				100%
# 102	White	Yes	Yes				None	2%			98%
# 103	White	Yes	Yes				None	3%			97%
# 104	White	Yes	Yes				None	2%			98%
# 105	White	Yes	Yes				None	3%			97%

Methodology : EPA Method 600/R-93-116

Page # 5

Date Analyzed : 14-Mar-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_




  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459





PLAN 1ST THRU 11TH FLOORS SECTOR C-2

1/8" = 1'-0"



Sample 104  
Floor tile covered with carpet  
Floor 4

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

Number	Color	% FIBROUS ASBESTOS						% NON-ASBESTOS FIBERS			
		Layered	Fibrous	Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 90	Tan	Yes	Yes				None	3%			97%
# 91	White	Yes	Yes				None	2%			98%
# 92	White	Yes	Yes				None	55%	30%		15%
# 93	White	Yes	Yes				None	12%			88%
# 94	White	Yes	Yes				None	58%	27%		15%
# 95	White	Yes	Yes				None	55%	25%		20%
# 96	White	Yes	Yes				None	2%			98%
# 97	White	Yes	Yes				None	8%			92%
# 98	White	Yes	Yes				None	3%			97%
# 99	Gray	Yes	Yes				None				100%
# 100	Green	Yes	Yes				None	2%			98%
# 101	Black	Yes	No				None				100%
# 102	White	Yes	Yes				None	2%			98%
# 103	White	Yes	Yes				None	3%			97%
# 104	White	Yes	Yes				None	2%			98%
# 105	White	Yes	Yes				None	3%			97%

Methodology : EPA Method 600/R-93-116

Page # 5

Date Analyzed : 14-Mar-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_




  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459





PLAN 1ST THRU 11TH FLOORS SECTOR C-2

1/8" = 1'-0"



Sample 105  
Floor tile covered with carpet  
Floor 5

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

Number	Color	% FIBROUS ASBESTOS						% NON-ASBESTOS FIBERS			
		Layered	Fibrous	Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 90	Tan	Yes	Yes				None	3%			97%
# 91	White	Yes	Yes				None	2%			98%
# 92	White	Yes	Yes				None	55%	30%		15%
# 93	White	Yes	Yes				None	12%			88%
# 94	White	Yes	Yes				None	58%	27%		15%
# 95	White	Yes	Yes				None	55%	25%		20%
# 96	White	Yes	Yes				None	2%			98%
# 97	White	Yes	Yes				None	8%			92%
# 98	White	Yes	Yes				None	3%			97%
# 99	Gray	Yes	Yes				None				100%
# 100	Green	Yes	Yes				None	2%			98%
# 101	Black	Yes	No				None				100%
# 102	White	Yes	Yes				None	2%			98%
# 103	White	Yes	Yes				None	3%			97%
# 104	White	Yes	Yes				None	2%			98%
# 105	White	Yes	Yes				None	3%			97%

Methodology : EPA Method 600/R-93-116

Page # 5

Date Analyzed : 14-Mar-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.


AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>3-6-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
--------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
98	Mens Restroom	1	ceiling	tile	white		
99A	105	1	floor	concrete	gray		
99B	105	1	floor	mastic	gray		
100	125B	1	floor	tile	green	12"	
101	125B	1	HVAC water unit	insulation	black		
102	near 210	2	floor	tile	white	12"	
103	319	3	floor	tile	white	12"	
104	429	4	floor	tile	white	12"	
105	507	5	floor	tile	white	12"	
Relinquished By: Signature			Received By: Signature			Date & Time	
Relinquished By: Signature			Received By: Signature			Date & Time	



134

REFLECTED CEILING PLAN  
TYPICAL ALL QUADRANTS

PERIMETER AIR COND.  
UNIT

CEILING ACCESS DOORS  
SEE DET. V/A-B1

TELEPHONE CLOSET  
V-13

TELEPHONE CLOSET  
V-14

STAIRS 1  
V-12

CHASE  
V-11

UP

DN

MEN  
V-16

Ceramic

CHASE  
V-17

CHASE  
V-18

V-8 VESTIBULE

ELECT. CLOS.  
V-10

ELEV. 1

SERVICE  
ELEV. 2

ELEV. 5

ELEV. 6

JANITOR  
V-19

SHAFT 'A'  
V-9

SHAFT 'B'  
V-20

133

ELEVATOR LOBBY  
V-26

SHAFT 'D'  
V-8

SHAFT 'C'  
V-21

ELECTRICAL CLOS.  
V-22

ELEV. 4

SERVICE  
ELEV. 3

ELEV. 8

ELEV. 7

MECH. CLOS.  
V-7

CHASE  
V-6

CHASE  
V-5

Ceramic

WOMEN  
V-4

V-3 VESTIBULE

DN

CHASE  
V-23

STAIRS 2  
V-24

TELEPHONE CLOSET  
V-2

TELEPHONE CLOSET  
V-25

OFFICE SPACE  
V-1

CARPET BEAM PATTERN  
TYPICAL ALL QUADRANTS

White tile around  
wall on sixth floor

PLAN 1ST THRU 11TH FLOORS SECTOR C-2

Sixth Floor  
Capital Plaza Office Tower

1/8" = 1'-0"



Sample 133  
Ceiling texture  
Floor 6



Sample 134  
Floor tile  
Floor 6

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 125	White	Yes	Yes				None	8%			92%
# 126	White	Yes	Yes				None	5%			95%
# 127	White	Yes	Yes				None	3%			97%
# 128 T	White	Yes	Yes				None	3%			97%
# 128 M	Tan	Yes	No				None	2%			98%
# 129	White	Yes	Yes				None	4%			96%
# 130	White	Yes	Yes				None	45%	30%		25%
# 131 T	White	Yes	Yes				None	2%			98%
# 131 M	Tan	Yes	No				None	3%			97%
# 132 T	White	Yes	Yes				None	3%			97%
# 132 M	Tan	Yes	No				None	2%			98%
# 133	White	Yes	Yes				None	5%			95%
# 134 T	White	Yes	Yes				None	3%			97%
# 134 M	Tan	Yes	No				None	3%			97%
# 135	White	Yes	Yes				None	10%	25%		65%
# 136	Yellow	Yes	Yes				None		99%		1%
# 137	White	Yes	Yes	< 1%				2%	10%		88%

Methodology : EPA Method 600/R-93-116

Page # 7

Date Analyzed : 11-Apr-14  
Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459


AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Nero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	<b>Lee Engineering, llc</b> P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
126	1109	11	floor	tile	white		
127	near 1019	10	floor	tile	white		
128	near 922	9	floor	tile	white		
129	Lobby	9	ceiling	texture	white		
130	Mens R	8	ceiling	tile	white		
131	821	8	floor	tile	white		
132	705	7	floor	tile	white		
133	Lobby	6	ceiling	texture	white		
134	614	6	floor	tile	white		
135	stair well	L/1	pipe wrapping	white wrapping	white		
136	stair well	L/1	pipe	insul	yellow		
137	stair well	L/1	elbow	plaster	gray		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



PLAN 1ST THRU 11TH FLOORS SECTOR C-2

Seventh Floor  
Capital Plaza Office Tower

1/8" = 1'-0"



Sample 132  
Floor tile  
Floor 7

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 125	White	Yes	Yes				None	8%			92%
# 126	White	Yes	Yes				None	5%			95%
# 127	White	Yes	Yes				None	3%			97%
# 128 T	White	Yes	Yes				None	3%			97%
# 128 M	Tan	Yes	No				None	2%			98%
# 129	White	Yes	Yes				None	4%			96%
# 130	White	Yes	Yes				None	45%	30%		25%
# 131 T	White	Yes	Yes				None	2%			98%
# 131 M	Tan	Yes	No				None	3%			97%
# 132 T	White	Yes	Yes				None	3%			97%
# 132 M	Tan	Yes	No				None	2%			98%
# 133	White	Yes	Yes				None	5%			95%
# 134 T	White	Yes	Yes				None	3%			97%
# 134 M	Tan	Yes	No				None	3%			97%
# 135	White	Yes	Yes				None	10%	25%		65%
# 136	Yellow	Yes	Yes				None		99%		1%
# 137	White	Yes	Yes	< 1%				2%	10%		88%

Methodology : EPA Method 600/R-93-116

Page # 7

Date Analyzed : 11-Apr-14  
 Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
 Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459


AJHA #1 02459

## Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Nero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
126	1109	11	floor	tile	white		
127	near 1019	10	floor	tile	white		
128	near 922	9	floor	tile	white		
129	Lobby	9	ceiling	texture	white		
130	Mens RR	8	ceiling	tile	white		
131	821	8	floor	tile	white		
132	705	7	floor	tile	white		
133	Lobby	6	ceiling	texture	white		
134	614	6	floor	tile	white		
135	stair well	L/1	pipe wrapping	white wrapping	white		
136	stair well	L/1	pipe	insul	yellow		
137	stair well	L/1	elbow	plaster	gray		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



PLAN 1ST THRU 11TH FLOORS SECTOR C-2

Eighth Floor  
Capital Plaza Office Tower

1/8" = 1'-0"



Sample 130  
Ceiling tile  
Floor 8



Sample 131  
Floor tile  
Floor 8

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 125	White	Yes	Yes				None	8%			92%
# 126	White	Yes	Yes				None	5%			95%
# 127	White	Yes	Yes				None	3%			97%
# 128 T	White	Yes	Yes				None	3%			97%
# 128 M	Tan	Yes	No				None	2%			98%
# 129	White	Yes	Yes				None	4%			96%
# 130	White	Yes	Yes				None	45%	30%		25%
# 131 T	White	Yes	Yes				None	2%			98%
# 131 M	Tan	Yes	No				None	3%			97%
# 132 T	White	Yes	Yes				None	3%			97%
# 132 M	Tan	Yes	No				None	2%			98%
# 133	White	Yes	Yes				None	5%			95%
# 134 T	White	Yes	Yes				None	3%			97%
# 134 M	Tan	Yes	No				None	3%			97%
# 135	White	Yes	Yes				None	10%	25%		65%
# 136	Yellow	Yes	Yes				None		99%		1%
# 137	White	Yes	Yes	< 1%				2%	10%		88%

Methodology : EPA Method 600/R-93-116

Page # 7

Date Analyzed : 11-Apr-14  
 Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
 Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459


AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Nero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
126	1109	11	floor	tile	white		
127	near 1019	10	floor	tile	white		
128	near 922	9	floor	tile	white		
129	Lobby	9	ceiling	texture	white		
130	Mens RR	8	ceiling	tile	white		
131	821	8	floor	tile	white		
132	705	7	floor	tile	white		
133	Lobby	6	ceiling	texture	white		
134	614	6	floor	tile	white		
135	stair well	L/1	Pipe wrapping	white wrapping	white		
136	stair well	L/1	pipe	insul	yellow		
137	stair well	L/1	elbow	plaster	gray		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



PLAN 1ST THRU 11TH FLOORS SECTOR C-2

Ninth Floor  
Capital Plaza Office Tower

1/8" = 1'-0"



Sample 128  
Floor tile  
Floor 9



Sample 129  
Ceiling texture  
Floor 9

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 125	White	Yes	Yes				None	8%			92%
# 126	White	Yes	Yes				None	5%			95%
# 127	White	Yes	Yes				None	3%			97%
# 128 T	White	Yes	Yes				None	3%			97%
# 128 M	Tan	Yes	No				None	2%			98%
# 129	White	Yes	Yes				None	4%			96%
# 130	White	Yes	Yes				None	45%	30%		25%
# 131 T	White	Yes	Yes				None	2%			98%
# 131 M	Tan	Yes	No				None	3%			97%
# 132 T	White	Yes	Yes				None	3%			97%
# 132 M	Tan	Yes	No				None	2%			98%
# 133	White	Yes	Yes				None	5%			95%
# 134 T	White	Yes	Yes				None	3%			97%
# 134 M	Tan	Yes	No				None	3%			97%
# 135	White	Yes	Yes				None	10%	25%		65%
# 136	Yellow	Yes	Yes				None		99%		1%
# 137	White	Yes	Yes	< 1%				2%	10%		88%

Methodology : EPA Method 600/R-93-116

Page # 7

Date Analyzed : 11-Apr-14  
Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_



  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459





127

REFLECTED CEILING PLAN  
TYPICAL ALL QUADRANTS

PERIMETER AIR COND.  
UNIT

CEILING ACCESS DOORS  
SEE DET. V/A-51

TELEPHONE CLOSET  
V-13

TELEPHONE CLOSET  
V-14

STAIRS 1  
V-12

CHASE  
V-11

UP

DN

V-10

V-11

V-12

V-13

V-14

V-15

V-16

V-17

V-18

V-19

V-20

V-21

V-22

V-23

V-24

V-25

Ceramic

ELEV. 1

SERVICE ELEV. 2

ELECT. CLOS.

V-7

V-10

V-11

V-12

V-13

V-14

V-15

V-16

V-17

V-18

V-19

V-20

V-21

V-22

V-23

V-24

V-25

JANITOR

V-19

SHAFT 'A'

V-9

ELEVATOR LOBBY

V-26

SHAFT 'D'

V-8

ELECTRICAL CLOS.

V-22

ELEV. 5

ELEV. 6

MECH. CLOS.

V-7

V-16

CHASE

V-6

CHASE

V-5

TELEPHONE CLOSET

V-2

WOMEN

V-4

VESTIBULE

V-3

V-2

V-1

V-17

V-18

V-19

V-20

V-21

V-22

V-23

V-24

V-25

OFFICE SPACE

V-1

CARPET BEAM PATTERN  
TYPICAL ALL QUADRANTS

PLAN 1ST THRU 11TH FLOORS SECTOR C-2

Tenth Floor  
Capital Plaza Office Tower

1/8" = 1'-0"



Sample 127  
Floor tile  
Floor 10

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 125	White	Yes	Yes				None	8%			92%
# 126	White	Yes	Yes				None	5%			95%
# 127	White	Yes	Yes				None	3%			97%
# 128 T	White	Yes	Yes				None	3%			97%
# 128 M	Tan	Yes	No				None	2%			98%
# 129	White	Yes	Yes				None	4%			96%
# 130	White	Yes	Yes				None	45%	30%		25%
# 131 T	White	Yes	Yes				None	2%			98%
# 131 M	Tan	Yes	No				None	3%			97%
# 132 T	White	Yes	Yes				None	3%			97%
# 132 M	Tan	Yes	No				None	2%			98%
# 133	White	Yes	Yes				None	5%			95%
# 134 T	White	Yes	Yes				None	3%			97%
# 134 M	Tan	Yes	No				None	3%			97%
# 135	White	Yes	Yes				None	10%	25%		65%
# 136	Yellow	Yes	Yes				None		99%		1%
# 137	White	Yes	Yes	< 1%				2%	10%		88%

Methodology : EPA Method 600/R-93-116

Page # 7


Date Analyzed : 11-Apr-14  
Analyst : Winterford MensahReviewed By: 

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459





PLAN 1ST THRU 11TH FLOORS SECTOR C-2

Eleventh Floor  
Capital Plaza Office Tower

1/8" = 1'-0"



Sample 125  
Ceiling plaster  
Floor 11



Sample 126  
Floor tile  
Floor 11

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 125	White	Yes	Yes				None	8%			92%
# 126	White	Yes	Yes				None	5%			95%
# 127	White	Yes	Yes				None	3%			97%
# 128 T	White	Yes	Yes				None	3%			97%
# 128 M	Tan	Yes	No				None	2%			98%
# 129	White	Yes	Yes				None	4%			96%
# 130	White	Yes	Yes				None	45%	30%		25%
# 131 T	White	Yes	Yes				None	2%			98%
# 131 M	Tan	Yes	No				None	3%			97%
# 132 T	White	Yes	Yes				None	3%			97%
# 132 M	Tan	Yes	No				None	2%			98%
# 133	White	Yes	Yes				None	5%			95%
# 134 T	White	Yes	Yes				None	3%			97%
# 134 M	Tan	Yes	No				None	3%			97%
# 135	White	Yes	Yes				None	10%	25%		65%
# 136	Yellow	Yes	Yes				None		99%		1%
# 137	White	Yes	Yes	< 1%				2%	10%		88%

Methodology : EPA Method 600/R-93-116

Page # 7

Date Analyzed : 11-Apr-14  
 Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
 Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time







Sample 124  
Floor tile  
Floor 12

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14  
Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_

  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459



AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



PLAN 13-A FLOOR SECTOR C-2

1/2" = 1'-0"

Color of pipe is indicated by sample number  
Red is default color



Sample 11  
Elbow pipe insulation  
Floor 13A



Sample 12  
Pipe wrap  
Floor13A



Sample 13  
Elbow insulation  
Floor 13A



Sample 14  
Pipe wrap  
Floor 13A



Sample 15  
Pipe wrap  
Floor 13A



Sample 16  
Pipe wrap  
Floor 13A



Sample 17  
Pipe wrap  
Floor 13A



Sample 18  
Pipe wrap  
Floor 13A



Sample 19  
Elbow  
Floor 13A



Sample 20  
Pipe wrap  
Floor 13A



Sample 21  
Pipe wrap  
Floor 13A



Sample 22  
Pipe wrap  
Floor 13A



Sample 23  
Elbow  
Floor 13A



Sample 24  
Debris - laying on top of unit  
Floor 13A



Sample 25  
Joint  
Floor 13A



Sample 26  
Pipe wrap  
Floor 13A



Sample 27  
Pipe wrap  
Floor 13A



Sample 28  
Joint/elbow  
Floor 13A



Sample 29  
Pipe wrap  
Floor 13A



Sample 30  
Pipe wrap  
Floor 13A



Sample 31  
Pipe wrap  
Floor 13A



Sample 32  
Valve  
Floor 13A



Sample 33  
Elbow  
Floor 13A



Sample 34  
Joint  
Floor 13A



Sample 35  
Pipe wrap  
Floor 13A



Sample 36  
Elbow  
Floor 13A



Sample 37  
Elbow  
Floor 13A



Sample 38  
Elbow  
Floor 13A



Sample 39  
Pipe insulation  
Floor 13A



Sample 40  
Pipe wrap  
Floor 13A



Sample 41  
Pipe wrap  
Floor 13A



Sample 42  
Pipe wrap  
Floor 13A



Sample 43  
Elbow  
Floor 13A



Sample 44  
Pipe wrap  
Floor 13A



Sample 45  
Pipe wrap  
Floor 13A



Sample 46  
Ceiling tile  
Floor 13A



Sample 47  
Pipe wrap  
Floor 13A

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 10	Yellow	Yes	Yes				None		99%		1%
# 11	Yellow	Yes	Yes				None		97%		3%
# 12	Yellow	Yes	Yes				None		99%		1%
# 13	Yellow	Yes	Yes				None		98%		2%
# 14	Yellow	Yes	Yes				None		99%		1%
# 15	White	Yes	Yes				None	3%	95%		2%
# 16	Yellow	Yes	Yes				None		97%		3%
# 17	Yellow	Yes	Yes				None		99%		1%
# 18	Yellow	Yes	Yes				None		97%		3%
# 19	Yellow	Yes	Yes				None		99%		1%
# 20	Yellow	Yes	Yes				None		97%		3%
# 21	Yellow	Yes	Yes				None	2%	97%		1%
# 22	Yellow	Yes	Yes				None		99%		1%
# 23	Yellow	Yes	Yes				None		97%		3%
# 24	White	Yes	Yes	35%				5%			60%
# 25	Yellow	Yes	Yes				None		99%		1%
# 26	Yellow	Yes	Yes				None		98%		2%
# 27	Yellow	Yes	Yes				None		99%		1%
# 28	White	Yes	Yes	5%				3%	52%		40%
# 29	Yellow	Yes	Yes				None		99%		1%

Methodology : EPA Method 600/R-93-116

Page # 1

Date Analyzed : 5-Mar-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 30	Black	Yes	Yes				None				100%
# 31	White	Yes	Yes	12%				3%	40%		45%
# 32	White	Yes	Yes	20%				5%	40%		35%
# 33	Yellow	Yes	Yes				None		99%		1%
# 34	Yellow	Yes	Yes				None		99%		1%
# 35	Yellow	Yes	Yes				None		97%		3%
# 36	White	Yes	Yes	15%				5%	45%		35%
# 37	Yellow	Yes	Yes	12%				3%	30%		55%
# 38	White	Yes	Yes	12%				5%	43%		40%
# 39	Yellow	Yes	Yes				None		99%		1%
# 40	Yellow	Yes	Yes				None		99%		1%
# 41	Yellow	Yes	Yes				None		98%		2%
# 42	Yellow	Yes	Yes				None		99%		1%
#43	White	Yes	Yes				None		98%		2%
#44	White	Yes	Yes	10%				5%	50%		35%
# 45	White	Yes	Yes	8%				2%	35%		55%
# 46	White	Yes	Yes				None	55%	35%		10%
# 47	Yellow	Yes	Yes				None		99%		1%
# 48	Yellow	Yes	Yes				None		97%		3%
# 49	Yellow	Yes	Yes				None		98%		2%

Methodology : EPA Method 600/R-93-116

Page # 2

Date Analyzed : 5-Mar-14  
Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>2-25-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	color of pipe Comments
10		13A	elbow	insulation	yellow	6 in. dia.	blue/yellow
11		13A	pipewrap	insulation	yellow	6 " "	blue/yellow
12		13A	valve	insulation	yellow	6 " "	blue/green
13		13A	elbow	insulation	white	6 " "	blue/green
14		13A	pipewrap	insulation	yellow	18 " "	yellow
15		13A	pipe wrap	insulation	yellow	24 " "	white/yellow
16		13A	pipewrap	insulation	yellow	18 " "	yellow
17		13A	pipe wrap	insulation	yellow	6 " "	yellow
18		13A	pipewrap	insulation	yellow	6 " "	yellow
19		13A	elbow	insulation	yellow	6 " "	yellow
20		13A	pipewrap	insulation	yellow	6 " "	yellow
21		13A	pipe wrap	insulation	yellow	18 " "	yellow
22		13A	pipewrap	insulation	yellow	18 " "	yellow
23		13A	elbow	insulation	yellow	18 " "	yellow
24		13A	pipewrap	insulation	white	3'4" loose	orange
25		13A	elbow	insulation	yellow	18 in dia	yellow
26		13A	pipewrap	insulation	yellow	18 " "	yellow
27		13A	pipewrap	insulation	yellow	8 " "	yellow
28		13A	elbow	insulation	white	14 " "	green
29		13A	pipewrap	insulation	yellow	18 " "	green



Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>2-25-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Color of pipe Comments
30		13A	pipewrap	insulation	black	18 in dia	green/white
31		13A	pipewrap	insulation	white	8 " "	green
32		13A	valve	insulation	white	8 " "	green
33		13A	elbow	insulation	white	4 " "	green
34		13A	elbow	insulation	yellow	4 " "	green
35		13A	pipewrap	insulation	yellow	4 " "	green
36		13A	elbow	insulation	white	8 " "	green
37		13A	elbow	insulation	white	6 " "	green
38		13A	elbow	insulation	white	4 " "	green
39		13A	pipewrap	insulation	yellow	8 " "	green
40		13A	pipewrap	insulation	yellow	6 " "	green
41		13A	pipewrap	insulation	yellow	4 " "	green
42		13A	pipewrap	insulation	yellow	8 " "	green
43		13A	elbow	insulation	white	8 " "	orange/white
44		13A	pipewrap	insulation	white	8 " "	orange/white
45		13A	pipewrap	insulation	white	8 " "	orange/white
46		13A	ceiling	tile	white		
47		13A	pipewrap	insulation	yellow	8 " "	white

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



PLAN 13-B FLOOR SECTOR C-2  
1/8" = 1'-0"



Sample 48  
Pipe wrap  
Floor 13B



Sample 49  
Pipe Wrap  
Floor 13B



Sample 50  
Pipe Wrap  
Floor 13B



Sample 51  
Pipe Wrap  
Floor 13B



Sample 52  
Pipe Wrap  
Floor 13B



Sample 53  
Pipe Wrap on valve  
Floor 13B

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 30	Black	Yes	Yes				None				100%
# 31	White	Yes	Yes	12%				3%	40%		45%
# 32	White	Yes	Yes	20%				5%	40%		35%
# 33	Yellow	Yes	Yes				None		99%		1%
# 34	Yellow	Yes	Yes				None		99%		1%
# 35	Yellow	Yes	Yes				None		97%		3%
# 36	White	Yes	Yes	15%				5%	45%		35%
# 37	Yellow	Yes	Yes	12%				3%	30%		55%
# 38	White	Yes	Yes	12%				5%	43%		40%
# 39	Yellow	Yes	Yes				None		99%		1%
# 40	Yellow	Yes	Yes				None		99%		1%
# 41	Yellow	Yes	Yes				None		98%		2%
# 42	Yellow	Yes	Yes				None		99%		1%
#43	White	Yes	Yes				None		98%		2%
#44	White	Yes	Yes	10%				5%	50%		35%
# 45	White	Yes	Yes	8%				2%	35%		55%
# 46	White	Yes	Yes				None	55%	35%		10%
# 47	Yellow	Yes	Yes				None		99%		1%
# 48	Yellow	Yes	Yes				None		97%		3%
# 49	Yellow	Yes	Yes				None		98%		2%

Methodology : EPA Method 600/R-93-116

Page # 2

Date Analyzed : 5-Mar-14  
Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 50	Yellow	Yes	Yes				None		98%		2%
# 51	White	Yes	Yes	15%				3%	37%		45%
# 52	White	Yes	Yes	12%				3%	40%		45%
# 53	White	Yes	Yes	12%				2%	38%		48%
# 54	Yellow	Yes	Yes				None	2%			98%
# 55	White	Yes	Yes				None	55%	30%		15%
# 56	White	Yes	Yes				None	98%			2%
# 57	Yellow	Yes	Yes				None		99%		1%
# 58	White	Yes	Yes	5%				3%	42%		50%
# 59	Yellow	Yes	Yes				None		98%		2%
# 60	White	Yes	Yes	10%				3%	52%		35%
# 61	Yellow	Yes	Yes				None		98%		2%
# 62	White	Yes	Yes	5%				2%	43%		50%
# 63	White	Yes	Yes				None	55%	40%		5%
# 64	White	Yes	Yes				None	5%			95%
# 65	Yellow	Yes	Yes				None		97%		3%
# 66	White	Yes	Yes	7%				3%	25%		65%
# 67	White	Yes	Yes	5%				2%	40%		55%
# 68	Yellow	Yes	Yes				None		99%		1%
# 69	Yellow	Yes	Yes				None		97%		3%

Methodology : EPA Method 600/R-93-116

Page # 3

Date Analyzed : 5-Mar-14  
Analyst : Winterford MensahReviewed By: 

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459


AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>2-25-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	color of pipe Comments
48		13B	pipewrap	insulation	yellow	8 in dia	white
49		13B	pipewrap	insulation	yellow	6 " "	white
50		13B	pipewrap	insulation	yellow	4 " "	white
51		13B	pipe wrap	insulation	white	4 " "	white
52		13B	pipewrap	insulation	white	8 " "	white
53		13B	valve	insulation	white	14 " "	white

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



14th FLOOR

Two - 1.5 inch copper pipes with asbestos containing insulation - approximately 300 linear feet

Approximate Scale:  
1 inch = 20 feet

Photo 3

Photo 4

Photo 2

Photo 1

Abated

5

4

3

2

1

6

8

7

10

9

3

4

WOMEN

MEN

TELE. CLO. #3

TELE. CLO. #4

TELE. CLO. #1

TELE. CLO. #2

ELE.

ELE.

ELE.

ELE.



Photo 1  
Pipes under floor tile  
Fourteenth Floor



Photo 2  
Insulation foil and pipe insulation  
Fourteenth Floor



Photo 3  
Black foam insulation  
Fourteenth Floor



Photo 4  
Joint compound  
Fourteenth Floor

332 West Broadway, Suite 613  
Louisville, Kentucky 40202

(502) 495-1212  
Fax: (502) 491-7111

**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2101259 Address: 500 Mero Street, Frankfort, KY  
Client Name: State Of Kentucky (Capital Plaza Office Tower)  
Sampled By: Bob Keiser - Lee Engineering LLC  
2A = Jacket Covering Insulation / 2B = Insulation

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 1	White	Yes	Yes	45%				3%			52%
# 2 A	Silver	Yes	Yes				None	5%	20%		75%
# 2 B	Yellow	Yes	Yes				None		98%		2%
# 3	Yellow	Yes	Yes				None		97%		3%
# 4	Black	Yes	No				None	2%			98%
# 5	Black	Yes	No				None				100%
# 6	White	Yes	Yes				None	5%			95%
# 7	White	Yes	Yes				None	3%			97%
# 8	Pink	Yes	Yes				None		99%		1%
# 9	White	Yes	Yes				None	8%			92%

Methodology : EPA Method 600/R-93-116  
Date Analyzed : 25-Jan-14  
Analyst : Winterford Mensah

Reviewed By:   
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.










SEE PLAN FLOOR 1 THRU 11  
SHEET A-25 FOR REFLECTED  
CEILING PLAN



PLAN 15<sup>TH</sup> THRU 23<sup>RD</sup> FLOORS SECTOR C-2

Fifteenth Floor  
Capital Plaza Office Tower



Sample 121  
Floor tile  
Floor 15



Sample 122  
Ceiling tile  
Floor 15



Sample 123  
Floor tile  
Floor 15

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody


Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



SEE PLAN FLOOR 1 THRU 11  
SHEET A-25 FOR REFLECTED  
CEILING PLAN



PLAN 15<sup>TH</sup> THRU 23<sup>RD</sup> FLOORS SECTOR C-2

Sixteenth Floor  
Capital Plaza Office Tower



Sample 120  
Floor tile  
Floor 16

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14  
 Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
 Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody


Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



SEE PLAN FLOOR 1 THRU 11  
SHEET A-25 FOR REFLECTED  
CEILING PLAN



PLAN 15<sup>TH</sup> THRU 23<sup>RD</sup> FLOORS SECTOR C-2

Seventeenth Floor  
Capital Plaza Office Tower



Sample 118  
Ceiling tile  
Floor 17



Sample 119  
Floor tile  
Floor 17

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody


Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time




SEE PLAN FLOOR 1 THRU 11  
SHEET A-25 FOR REFLECTED  
CEILING PLAN



PLAN 15<sup>TH</sup> THRU 23<sup>RD</sup> FLOORS SECTOR C-2

Eighteenth Floor  
Capital Plaza Office Tower



Sample 116  
Ceiling tile  
Floor 18



Sample 117  
Floor tile  
Floor 18

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody


Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



SEE PLAN FLOOR 1 THRU 11  
SHEET A-25 FOR REFLECTED  
CEILING PLAN



No tile on this floor  
Concrete under carpet

115

Ceramic

Ceramic

TYPICAL CARPET SEAM PATTERN



Sample 115  
Ceiling tile  
Floor 19

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody


Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



SEE PLAN FLOOR 1 THRU 11  
SHEET A-25 FOR REFLECTED  
CEILING PLAN



114

PLAN 15<sup>TH</sup> THRU 23<sup>RD</sup> FLOORS SECTOR C-2

Twentieth Floor  
Capital Plaza Office Tower



Sample 114  
Floor tile  
Floor 20

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14  
Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_

  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody


Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



SEE PLAN FLOOR 1 THRU 11  
SHEET A-25 FOR REFLECTED  
CEILING PLAN



111

112

113

Twenty-first floor  
Capital Plaza Office Tower

PLAN 15<sup>TH</sup> THRU 23<sup>RD</sup> FLOORS SECTOR C-2



Sample 111  
Ceiling tile  
Floor 21



Sample 112  
Ceiling tile  
Floor 21



Sample 113  
Floor tile  
Floor 21

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody


Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



SEE PLAN FLOOR 1 THRU 11  
SHEET A-25 FOR REFLECTED  
CEILING PLAN



110



Sample 110  
Floor tile  
Floor 22

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody


Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time




SEE PLAN FLOOR 1 THRU 11  
SHEET A-25 FOR REFLECTED  
CEILING PLAN



PLAN 15<sup>TH</sup> THRU 23<sup>RD</sup> FLOORS SECTOR C-2

Twenty-third Floor  
Capital Plaza Office Tower



Sample 108  
Ceiling tile  
Floor 23



Sample 109  
Floor tile  
Floor 23

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459


AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time



PLAN 24<sup>TH</sup> FLOOR SECTOR C-2

1/8" = 1'-0"

Twenty-fourth Floor  
Capital Plaza Office Tower



Sample 106  
Ceiling plaster  
Floor 24



Sample 107  
Floor tile  
Floor 24

332 West Broadway, Suite 613  
Louisville, Kentucky 40202(502) 495-1212  
Fax: (502) 491-7111**BULK SAMPLE ASBESTOS ANALYSIS**

Analysis N# 2104011 Address: 500 Mero Street  
 Client Name: State Of KY Frankfort, KY  
 Sampled By: Bob Keiser (Capital Plaza Office Tower)

T = Floor Tile / M = Mastic Under The Floor Tile

Number	Color	Layered	Fibrous	% FIBROUS ASBESTOS				% NON-ASBESTOS FIBERS			
				Chrysotile	Amosite	crocidolite	Others	Cellulose	Fiberglass	Syn. Fiber	Other/Mat.
# 106	White	Yes	Yes				None	5%			95%
# 107	Gray	Yes	Yes				None	2%			98%
# 108	White	Yes	Yes				None	5%			95%
# 109	White	Yes	Yes				None	2%			98%
# 110	White	Yes	Yes				None	3%			97%
# 111	White	Yes	Yes				None	8%			92%
# 112	White	Yes	Yes				None	5%			95%
# 113	White	Yes	Yes				None	2%			98%
#114	White	Yes	Yes				None	2%			98%
# 115	White	Yes	Yes				None	45%	30%		25%
# 116	White	Yes	Yes				None	48%	27%		25%
# 117	White	Yes	Yes				None	3%			97%
# 118	White	Yes	Yes				None	5%			95%
# 119	White	Yes	Yes				None	3%			97%
# 120	White	Yes	Yes				None	2%			98%
# 121 T	Gray	Yes	Yes				None	3%			97%
# 121 M	Black	Yes	No	2%				2%			98%
# 122	White	Yes	Yes				None	45%	30%		25%
# 123	White	Yes	Yes				None	2%			98%
# 124	White	Yes	Yes				None	2%			98%

Methodology : EPA Method 600/R-93-116

Page # 6

Date Analyzed : 4-Apr-14Analyst : Winterford Mensah

Reviewed By: \_\_\_\_\_


  
Signature

The test relates only to the items tested. This report does not represent endorsement by NVLAP or any agency of the U.S Government. Partial Reproduction of any part of this report is strictly prohibited. Samples shall be retained for (30) days.

AIHA # 102459

AJHA #1 02459

### Asbestos Inspection Form and Chain of Custody

Project: <u>Capital Plaza Office Tower</u> Date: <u>3-26-14</u> Address: <u>500 Mero Street, Frankfort</u> Sampled By: <u>Bob Keiser</u>	Lee Engineering, llc P.O. Box 500 Lawrenceburg, KY 40341 Ph (502)600-0016
---------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

Sample #	Room #	Floor #	Location	Matrix	Color	Size	Comments
106	Lobby	24	ceiling	plaster	white		
107	2414	24	floor	tile	gray		
108	Lobby	23	ceiling	tile	white		
109	2312	23	floor	tile	white	covered	with carpet
110	2204A	22	floor	tile	white		
111	Mess	21	ceiling	tile	white		
112		21	ceiling	tile	white		
113		21	floor	tile	white		
114		20	floor	tile	white		
115		19	ceiling	tile	white		
116		18	ceiling	tile	white		
117	1806	18	floor	tile	white		
118	Lobby	17	ceiling	tile	white		
119	1709	17	floor	tile	white		
120	1625	16	floor	tile	white		
121		15	floor	tile	gray		
122		15	ceiling	tile	white		
123	1522	15	floor	tile	white		
124	1205	12	floor	tile	white		
125	Lobby	11	ceiling	plaster	white		

Relinquished By: Signature	Received By: Signature	Date & Time
Relinquished By: Signature	Received By: Signature	Date & Time

**Lee Engineering, LLC**  
**Environment & Infrastructure**

**P.O. Box 500**  
**Lawrenceburg, KY 40342**  
**(502) 859-0190 ♦ (502) 859-3000 fax**  
**[jleeeng@bellsouth.net](mailto:jleeeng@bellsouth.net)**

**LIMITED ASBESTOS SURVEY AT**

**Capitol Tower  
500 Mero Drive  
Frankfort, KY 40601**

**For:  
Maziar Torabi, PE  
Division of Engineering,  
Dept. for Facilities & Support Services  
Bush Building, 403 Wapping Street  
Frankfort, KY 40601**

***Air Source Technology, Inc.*  
160 Prosperous Place, Suite 201  
Lexington, Kentucky 40509**

**Report Date: March 15, 2012**

**ASTI Project # C7530**

## Table of Contents

<b>Section</b>	<b>Page</b>
<b>INTRODUCTION &amp; PROTOCOL.....</b>	<b>1</b>
<b>SUMMARY OF LAB RESULTS FOR SUSPECT ACBM .....</b>	<b>2</b>
<b>APPLICABLE REFERENCES.....</b>	<b>4</b>
<b>PHOTOGRAPHS .....</b>	<b>Appendix A</b>
<b>LABORATORY REPORTS.....</b>	<b>Appendix B</b>
<b>SAMPLE LOCATIONS .....</b>	<b>Appendix C</b>

## **Introduction & Protocol**

**INTRODUCTION:** As part of an assessment for future renovations at the Capitol Tower, located in Frankfort, KY, Air Source Technology, Inc (ASTI) conducted a limited asbestos survey for the Kentucky Division of Engineering & Contract Administration.

**SURVEY PROTOCOL:** The survey work was performed in accordance with applicable hazardous material regulations and standards as established by the United States Environmental Protection Agency and the Commonwealth of Kentucky. In general, ASTI followed the survey protocol outlined in ASTM International (ASTM) Document E2308-05, Standard Guide for Limited Asbestos Screens of Buildings.

### Summary of Lab Results for Suspect ACBM

Suspect Asbestos Building Material Samples		
Sample ID	Description/ Location	Asbestos (%)
CT-24-1a	12" Floor Tile: White with grey/ 24 <sup>th</sup> Floor Perimeter	NAD
CT-24-1a	Yellow Mastic/ 24 <sup>th</sup> Floor Perimeter	NAD
CT-24-2	2'x2' Drop Ceiling Tile/ 24 <sup>th</sup> Floor Lobby	NAD
CT-24-3	2'x2' Drop Ceiling Tile/ 24 <sup>th</sup> Floor Lobby	NAD
CT-24-4	2'x2' Drop Ceiling Tile/ 24 <sup>th</sup> Floor Lobby	NAD
CT-23-1	Plaster Ceiling/ 23 <sup>rd</sup> Floor Core	NAD
CT-15-1a	12" Floor Tile: Grey/ 15 <sup>th</sup> Floor Lobby	0.75% Chrysotile*
CT-15-1b	Black Mastic/ 15 <sup>th</sup> Floor Lobby	NAD
CT-15-2a	12" Floor Tile: Grey/ 15 <sup>th</sup> Floor Lobby	Not Analyzed
CT-15-2b	Black Mastic/ 15 <sup>th</sup> Floor Lobby	NAD
CT-15-3a	12" Floor Tile: Grey/ 15 <sup>th</sup> Floor Lobby	Not Analyzed
CT-15-3b	Black Mastic/ 15 <sup>th</sup> Floor Lobby	NAD
CT-15-4a	Blue Mastic/ 15 <sup>th</sup> Floor Perimeter	NAD
CT-15-4b	12" Floor Tile: White/ 15 <sup>th</sup> Floor Perimeter	NAD
CT-15-4c	Yellow Mastic/ 15 <sup>th</sup> Floor Perimeter	NAD
CT-1 (14 <sup>th</sup> )	<b>3" Pipe Insulation/ 14<sup>th</sup> Floor Server Room</b>	<b>6% Chrysotile 12% Amosite</b>
CT-2a (14 <sup>th</sup> )	<b>12" Floor Tile: White/ 14<sup>th</sup> Floor Vault</b>	<b>2% Chrysotile</b>
CT-2b (14 <sup>th</sup> )	<b>Black Mastic</b>	<b>5% Chrysotile</b>
CT-3 (14 <sup>th</sup> )	2'x2' Drop Ceiling Tile/ 14 <sup>th</sup> Floor	NAD
CT-4 (14 <sup>th</sup> )	Ceiling Plaster/ Central Halls & Closets/ 14 <sup>th</sup> Floor	NAD
CT-5 (14 <sup>th</sup> )	<b>3" Pipe Joint Compound/ Pipe Chase/ 14<sup>th</sup> Floor</b>	<b>8% Chrysotile 2% Amosite</b>
CT-6 (14 <sup>th</sup> )	6" Pipe Joint Compound/ 14 <sup>th</sup> Floor Maintenance Closet	NAD
CT-7a (14 <sup>th</sup> )	<b>12" Floor Tile: White/ 14<sup>th</sup> Floor Vault</b>	<b>4% Chrysotile</b>
CT-7b (14 <sup>th</sup> )	<b>Black Mastic</b>	<b>3% Chrysotile</b>
CT-8 (14 <sup>th</sup> )	2'x2' Drop Ceiling Tile/ 14 <sup>th</sup> Floor	NAD
CT-9 (14 <sup>th</sup> )	Ceiling Plaster/ 14 <sup>th</sup> Floor Central Halls & Closets	NAD
CT-13-1	<b>Fire Door Insulation/ 13<sup>th</sup> Floor</b>	<b>5% Chrysotile 15% Amosite</b>
CT-1-1a	12" Floor Tile: Green/ 1 <sup>st</sup> Floor Perimeter	NAD
CT-1-1b	Yellow Mastic/ 1 <sup>st</sup> Floor Perimeter	NAD
CT-Lobby-1a	12" Floor Tile: White/ Lobby Mr. Dyer's Office	NAD
CT-Lobby-1b	Yellow Mastic/ Lobby Mr. Dyer's Office	NAD
CT-Lobby-2	2'x2' Drop Ceiling Tile/ Lobby Mr. Dyer's Office	NAD

\*Note: Results of Point Count Analysis

Suspect Asbestos Building Material Samples		
Sample ID	Description/ Location	Asbestos (%)
CT-Mez-1	2'x4' Drop Ceiling Tile/ Mezzanine Lobby	NAD
CT-Mez-2	2'x4' Drop Ceiling Tile/ Mezzanine Lobby	NAD
CT-Mez-3	2'x4' Drop Ceiling Tile/ Mezzanine Lobby	NAD
CT-Mez-4	Textured Ceiling/ Mezzanine Lobby	0.50% Chrysotile*
CT-Mez-5	Textured Ceiling/ Mezzanine Lobby	0.25% Chrysotile*
CT-Mez-6	Textured Ceiling/ Mezzanine Lobby	0.50% Chrysotile*
CT-Mez-7a	Yellow Mastic/ Mezzanine Nurse's Station	NAD
CT-Mez-7b	<b>12" Floor Tile: Cream/ Mezzanine Nurse's Station</b>	<b>1.0% Chrysotile*</b>
CT-Mez-8	3'x3' Drop Ceiling Tile/ Mezzanine	NAD
CT-Mez-9	3'x3' Drop Ceiling Tile/ Mezzanine	NAD
CT-Mez-10	3'x3' Drop Ceiling Tile/ Mezzanine	NAD
CT-Mez-11a	12" Floor Tile: Tan/ Mezzanine Mail	0.75% Chrysotile*
CT-Mez-11b	<b>Black Mastic/ Mezzanine Mail</b>	<b>1.25% Chrysotile*</b>
CT-Mez-12	12" Floor Tile: Tan/ Mezzanine Mail	Not Analyzed
CT-Mez-13	12" Floor Tile: Tan/ Mezzanine Mail	Not Analyzed
CT-Mez-14	2'x4' Drop Ceiling Tile/ Mezzanine Mail	NAD
CT-Mez-15	2'x4' Drop Ceiling Tile/ Mezzanine Mail	NAD
CT-Mez-16	2'x4' Drop Ceiling Tile/ Mezzanine Mail	NAD
CT-Ground-1	Boiler Flue Insulation/ Ground Floor Boiler Room	NAD
CT-Ground-2	Boiler Flue Insulation/ Ground Floor Boiler Room	NAD
CT-Ground-3	Boiler Flue Insulation/ Ground Floor Boiler Room	NAD
CT-Ground-4	2'x2' Drop Ceiling Tile (cloth face)/ Ground Floor Hallway	NAD
CT-Ground-5	2'x2' Drop Ceiling Tile (cloth face)/ Ground Floor Hallway	NAD
CT-Ground-6	2'x2' Drop Ceiling Tile (cloth face)/ Ground Floor Hallway	NAD

\*Note: Results of Point Count Analysis

Asbestos containing materials were identified as the 12" floor tile (and associated black mastic), fire door insulation, pipe insulation, and pipe joint compound. Boiler insulation and gaskets are assumed to be positive. See Appendix A for photographs of sample locations. See Appendix B for laboratory analyses.

Quantities of pipe insulation/joint compound can only be estimated at this time due to occupancy/usage of the areas. A destructive survey would be required to quantify ACBM in pipe chases and to determine if asbestos containing materials are found within the partition walls.

ACBM Material	Estimated Quantity	Estimated Removal Cost
Floor tile and black mastic	970 ft <sup>2</sup>	\$9,000
Pipe Insulation	1500 linear feet	\$15,000
Pipe Joint Compound	2000	\$60,000
Fire Door	70	\$3,500


## APPLICABLE REFERENCES

1. U. S. Environmental Protection Agency (EPA):
  - A. Title 40, Code of Federal Regulations, Part 763, Subpart E, Asbestos Containing Materials in Schools.
  - B. Title 40, Code of Federal Regulations, Part 61, Subpart A, Regulation for Asbestos.
  - C. Title 40, Code of Federal Regulations, Part 61, Subpart M (Revised Subpart B), National Emissions Standards for Hazardous Air Pollutants.
  
2. Commonwealth of Kentucky:
  - A. Kentucky Natural Resources and Environmental Protection Cabinet, Division for Air Quality 401 KAR 58:005 (accreditation of asbestos professionals), 401 KAR 58:025 (asbestos NESHAPS standards), 401 KAR 58:010 (AHERA requirements for schools), and 401 KAR 58:040 (certification and work-practice requirements for abatement entities).
  - B. Kentucky Division of Occupational Safety & Health Revisions to Adopted 29 CFR Part 1926.1101, Asbestos, Tremolite, Anthophyllite, and Actinolite. Also revisions to Amended 29 CFR Part 1910.1001, Occupational Exposure to Asbestos, Tremolite, Anthophyllite, and Actinolite.
  - C. Kentucky Natural Resources and Environmental Protection, Division of Waste Management, Recommended Procedures for Treatment and Disposal of Asbestos Waste.
  
3. American Society for Testing and Materials (ASTM):
  - A. ASTM International, Designation E2308-5, Standard Guide for Limited Asbestos Screens of Buildings.


**Appendix A**  
**Photographs**



Photograph #1: Sample CT-24-1: 12" Floor Tile (white).



Photograph #2: Samples CT-24-2, CT-24-3 & CT-24-4: 2'x2' Drop Ceiling Tile




Photograph #3: Sample CT-23-1: Plaster Ceiling



Photograph #4: Sample CT-15-1, CT-15-2 & CT-15-3: 12" Floor Tile (grey).



Photograph #5: Sample CT-15-4" 12" Floor Tile (white).



Photograph #6: Sample CT-1: 3" Pipe Insulation.



Photograph #7: Sample CT-2 & CT-7: 12" white floor tile with black mastic.




Photograph #8: Sample CT-3 & CT-8: 2'x2' Drop Ceiling Tile.



Photograph #9: Sample CT-4 & CT-9: Plaster Ceilings.




Photograph #10: Sample CT-5: 3" Pipe Joint Compound.




Photograph #11: Sample CT-6: 6" Pipe Joint Compound.




Photograph #12: Mercury containing thermostats located in the server rooms.




Photograph #13: The interior of partition walls and doors needs to be accessed.




Photograph #14: Sample CT-13b-1: Fire Door Insulation.



Photograph #15: Sample CT-1-1: 12" Floor Tile (green).



Photograph #16: Sample CT-Lobby-1: 12" Floor Tile (white).




Photograph #17: Sample CT-Lobby-2: 2'x2' Drop Ceiling Tile.



Photograph #18: Sample CT-Mez-1, CT-Mez-2 & CT-Mez-3: 2'x4' Drop Ceiling Tile.




Photograph #19: Sample CT-Mez-4, CT-Mez-5 & CT-Mez-6: Textured Ceiling




Photograph #20: Sample CT-Mez-7, CT-Mez-11, CT-Mez-12 & CT-Mez-13: 12" Floor Tile (white with brown streaks)



Photograph #21: Sample CT-Mez-8, CT-Mez-9 & CT-Mez-10: '3'x3' Drop Ceiling Tile.



Photograph #22: Sample CT-Mez-14, CT-Mez-15 & CT-Mez-16: 2'x4' Drop Ceiling Tile.



Photograph #23: Sample CT-Ground-1, CT-Ground-2 & CT-Ground-3: Boiler Flue Compound



Photograph #24: Sample CT-Ground-4, CT-Ground-5 & CT-Ground-6: 2'x2' Drop Ceiling Tile.

**Appendix B**  
**Laboratory Reports**



# Asbestos Bulk Analysis Report

Environmental Hazards Services, L.L.C.  
7469 Whitepine Rd  
Richmond, VA 23237

Telephone: 800.347.4010

Report Number: 12-03-00631

Client: Air Source Technology Inc.  
160 Prosperous Pl. Ste. 201  
Lexington, KY 40509

Received Date: 03/06/2012  
Analyzed Date: 03/08/2012  
Reported Date: 03/08/2012

Project/Test Address: C7530; Commonwealth of KY (Capital Tower); Frankfort, KY PO 105937

Client Number:  
18-4340

Fax Number:  
859-299-0494

## Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-03-00631-001	CT-13b-1		White Fibrous	5% Chrysotile 15% Amosite	80% Non-Fibrous
				Total Asbestos: 20%	
12-03-00631-002A	CT-24-1	Tile	White Vinyl	NAD	100% Non-Fibrous
12-03-00631-002B	CT-24-1	Mastic	Yellow Adhesive	NAD	2% Synthetic 98% Non-Fibrous
12-03-00631-003	CT-24-2		White Fibrous; Silver Foil-Like	NAD	1% Cellulose 85% Fibrous Glass 14% Non-Fibrous
12-03-00631-004	CT-24-3		White Fibrous	NAD	85% Fibrous Glass 15% Non-Fibrous

## Environmental Hazards Services, L.L.C

Client Number: 18-4340  
 Project/Test Address: C7530; Commonwealth of KY (Capital Tower); Frankfort, KY PO 105937

Report Number: 12-03-00631

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-03-00631-005	CT-24-4		White Fibrous; Silver Foil-Like	NAD	1% Cellulose 85% Fibrous Glass 14% Non-Fibrous
12-03-00631-006	CT-23-1		White/Gray Granular	NAD	100% Non-Fibrous
12-03-00631-007A	CT-15-1	Tile	Gray Vinyl	2% Chrysotile	98% Non-Fibrous
				Total Asbestos: 2%	
12-03-00631-007B	CT-15-1	Mastic	Black Adhesive	NAD	2% Cellulose 98% Non-Fibrous
12-03-00631-008A	CT-15-2	Tile		Did Not Analyze (Positive Stop)	
12-03-00631-008B	CT-15-2	Mastic	Black Adhesive	NAD	100% Non-Fibrous
12-03-00631-009A	CT-15-3	Tile		Did Not Analyze (Positive Stop)	
12-03-00631-009B	CT-15-3	Mastic	Black Adhesive	NAD	2% Cellulose 98% Non-Fibrous
12-03-00631-010A	CT-15-4	Mastic	Blue Adhesive	NAD	1% Cellulose 99% Non-Fibrous

## Environmental Hazards Services, L.L.C

Client Number: 18-4340  
 Project/Test Address: C7530; Commonwealth of KY (Capital Tower); Frankfort, KY PO 105937

Report Number: 12-03-00631

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-03-00631-010B	CT-15-4	Tile	White Vinyl	NAD	100% Non-Fibrous
12-03-00631-010C	CT-15-4	Mastic	Yellow Adhesive	NAD	2% Cellulose 98% Non-Fibrous
12-03-00631-011A	CT-1-1	Tile	Green Vinyl	NAD	100% Non-Fibrous
12-03-00631-011B	CT-1-1	Mastic	Yellow Adhesive	NAD	2% Synthetic 98% Non-Fibrous
12-03-00631-012A	CT-Lobby-1	Tile	White Vinyl	NAD	100% Non-Fibrous
12-03-00631-012B	CT-Lobby-1	Mastic	Yellow Adhesive	NAD	2% Cellulose 98% Non-Fibrous
12-03-00631-013	CT-Lobby-2		Gray/White Fibrous	NAD	55% Cellulose 35% Fibrous Glass 10% Non-Fibrous
12-03-00631-014	CT-Mez-1		Gray/White Fibrous	NAD	55% Cellulose 35% Fibrous Glass 10% Non-Fibrous

## Environmental Hazards Services, L.L.C

Client Number: 18-4340  
 Project/Test Address: C7530; Commonwealth of KY (Capital Tower); Frankfort, KY PO 105937

Report Number: 12-03-00631

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-03-00631-015	CT-Mez-2		Gray/White Fibrous	NAD	55% Cellulose 35% Fibrous Glass 10% Non-Fibrous
12-03-00631-016	CT-Mez-3		Gray/White Fibrous	NAD	55% Cellulose 35% Fibrous Glass 10% Non-Fibrous
12-03-00631-017	CT-Mez-4		White Textured Fibrous	Trace <1% Chrysotile	75% Cellulose 25% Non-Fibrous
				Total Asbestos: Trace <1%	
12-03-00631-018	CT-Mez-5		White Textured Fibrous	Trace <1% Chrysotile	65% Cellulose 35% Non-Fibrous
				Total Asbestos: Trace <1%	
12-03-00631-019	CT-Mez-6		White Textured Fibrous	Trace <1% Chrysotile	70% Cellulose 30% Non-Fibrous
				Total Asbestos: Trace <1%	
12-03-00631-020A	CT-Mez-7	Top Mastic	Yellow Adhesive	NAD	3% Cellulose 97% Non-Fibrous
12-03-00631-020B	CT-Mez-7	Tile	Tan Vinyl	2% Chrysotile	98% Non-Fibrous
				Total Asbestos: 2%	
12-03-00631-021	CT-Mez-8		Gray Fibrous	NAD	75% Fibrous Glass 25% Non-Fibrous

## Environmental Hazards Services, L.L.C

Client Number: 18-4340  
 Project/Test Address: C7530; Commonwealth of KY (Capital Tower); Frankfort, KY PO 105937

Report Number: 12-03-00631

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-03-00631-022	CT-Mez-9		Gray Fibrous	NAD	75% Fibrous Glass 25% Non-Fibrous
12-03-00631-023	CT-Mez-10		Gray Fibrous	NAD	75% Fibrous Glass 25% Non-Fibrous
12-03-00631-024A	CT-Mez-11	Tile	White Vinyl	2% Chrysotile	98% Non-Fibrous
				Total Asbestos: 2%	
12-03-00631-024B	CT-Mez-11	Mastic	Black Adhesive	2% Chrysotile	3% Cellulose 95% Non-Fibrous
				Total Asbestos: 2%	
12-03-00631-025A	CT-Mez-12	Tile		Did Not Analyze (Positive Stop)	
12-03-00631-025B	CT-Mez-12	Mastic		Did Not Analyze (Positive Stop)	
12-03-00631-026A	Ct-Mez-13	Tile		Did Not Analyze (Positive Stop)	
12-03-00631-026B	CT-Mez-13	Mastic		Did Not Analyze (Positive Stop)	
12-03-00631-027	CT-Mez-14		Beige Fibrous	NAD	85% Fibrous Glass 15% Non-Fibrous

## Environmental Hazards Services, L.L.C

Client Number: 18-4340  
 Project/Test Address: C7530; Commonwealth of KY (Capital Tower); Frankfort, KY PO 105937

Report Number: 12-03-00631

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-03-00631-028	CT-Mez-15		Beige Fibrous	NAD	85% Fibrous Glass 15% Non-Fibrous
12-03-00631-029	CT-Mez-16		Beige Fibrous	NAD	85% Fibrous Glass 15% Non-Fibrous
12-03-00631-030	CT-Ground-1		Gray Fibrous	NAD	35% Fibrous Glass 65% Non-Fibrous
12-03-00631-031	CT-Ground-2		Gray Fibrous	NAD	35% Fibrous Glass 65% Non-Fibrous
12-03-00631-032	CT-Ground-3		Gray Fibrous	NAD	35% Fibrous Glass 65% Non-Fibrous
12-03-00631-033	CT-Ground-4		White Fibrous; White Vinyl-Like	NAD	90% Fibrous Glass 10% Non-Fibrous
12-03-00631-034	CT-Ground-5		White Fibrous; White Vinyl-Like	NAD	90% Fibrous Glass 10% Non-Fibrous
12-03-00631-035	CT-Ground-6		White Fibrous; White Vinyl-Like	NAD	90% Fibrous Glass 10% Non-Fibrous

# Environmental Hazards Services, L.L.C

Client Number: 18-4340  
Project/Test Address: C7530; Commonwealth of KY (Capital Tower); Frankfort, KY PO 105937

Report Number: 12-03-00631

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
-------------------	----------------------	------------	-----------------------	----------	-----------------

QC Sample: 60-NY-35-3829  
QC Blank: SRM 1866 Fiberglass  
Reporting Limit: 1% Asbestos  
Method: EPA Method 600/R-93/116  
Analyst: Kathy Sizemore



Reviewed By Authorized Signatory: \_\_\_\_\_

Irma Faszewski  
QA/QC Manager

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

\* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected

35 RUN



# Asbestos Chain-of-Custody

Environmental Hazards Services, LLC  
www.leadlab.com 7469 Whitepine Rd  
(800)347-4010 Richmond, VA  
(804)275-4907 (fax) 23237

Company Name: Air Source Technology Inc.  
Phone: (859)299-0046

Address: 160 Prosperous Pl. Ste. 201,  
Fax: 859-299-0494 E

City/State/Zip: Lexington, KY 40509

Project Name/Testing Address: 17530; Commonwealth of KY (Capitol Power)  
E-mail: support@air-sourcetechnology.com

Acct Number: 18-4340

City/State (required) Frankfort, KY

Collected by: CHA Certification Number: \_\_\_\_\_

Purchase Order Number: 105937

Turn Around Times: 1 - Day  2 - Day  3 - Day  Weekend (Must Call Ahead)

*If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

No.	Client Sample ID	Date Collected	ASBESTOS						AIR			COMMENTS		
			PM	PM Point Count 400	PM NY Protocol	PCM	TEM Chilled (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)		Total Time (traces)	Volume (Total Liters)
1	CF-136-1	2/25/12	X											Eye Area Evaluation
2	CF-24-1													12" Floor Tile (white)
3	CF-24-2													2" x 2" Deep Ceiling Tile
4	CF-24-3													"
5	CF-24-4													"
6	CF-23-1													"
7	CF-15-1													Plaster Ceiling
8	CF-15-2													12" Floor Tile (grey) w/ Black Mask
9	CF-15-3													"
10	CF-15-4													"

Sample fill positive

Sample fill positive

Signature: Chris Adkins

Released by: Chris Adkins  
Received by: K IYLEK

Date/Time: 3/1/12

3/1/12



Environmental Hazards Services, LLC

www.leadlab.com 7469 Whitepine Rd  
(800)347-4010 Richmond, VA  
(804)275-4907 (fax) 23237

# Asbestos Chain-of-Custody

~ For Lab Use Only ~

Company Name: Air Source Technology Inc. Address: 160 Prosperous Pl. Ste. 201  
City/State/Zip: Lexington, KY 40509  
Phone: (859)299-0046 Fax: 859-299-0494 E  
Project Name/Testing Address: C7530; Commonwealth of KY (Capital Tower) E-mail: support@airsourcetechnology.com  
City/State (required): Frankfort, KY  
Acct. Number: 18-4340  
Collected by: CHA Certification Number: 105937  
Purchase Order Number: 105937

Turn Around Times: 3 - Day  Same Day (Must Call Ahead)  Weekend (Must Call Ahead)

*If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

No.	Client Sample ID	Date Collected	ASBESTOS						AIR			Volume (Total Liters)	COMMENTS	
			PLM	PLM Print Count 400	PLM Print Count 1000	TM NY Protocol	ROM	TEM Certified (Bulk)	TEM/HERA (Air)	Time On	Time Off			Flow Rate (L/min)
1	CT-1-1	2/29/12	X											12" Floor Tile (Green)
2	CT-Lobby-1													12" Floor Tile (white)
3	CT-Lobby-2													2x2 Drop Ceiling Tile
4	CT-Mez-1													2x4 Drop Ceiling Tile
5	CT-Mez-2													"
6	CT-Mez-3													"
7	CT-Mez-4													"
8	CT-Mez-5													Aspen Ceiling
9	CT-Mez-6													"
10	CT-Mez-7													12" Floor Tile (Green)

Sample #1 positive  
Sample #11 positive

Released by: Chris Adkins Signature: [Signature]  
Received by: K W L E A Signature: [Signature]  
Date/Time: 3/1/12 3:11 PM



**EHS**  
Laboratories

Environmental Hazards Services, LLC  
www.leadlab.com 7469 Whitepine Rd  
(800)347-4010 Richmond, VA  
(804)275-4907 (fax) 23237

# Asbestos Chain-of-Custody

~ For Lab Use Only ~

Company Name: Air Source Technology Inc.

Phone: (859)299-0046

Project Name/Testing Address: C7530, Commonwealth of Ky (Capitol Tower)

Collected by: CH A

Address: 160 Prosperous Pl. Ste. 201,

Fax: 859-299-0494 E

E-mail: support@airsourcetechnology.com

Certification Number: \_\_\_\_\_

City/State/Zip: Lexington, KY 40509

Acct. Number: 18-4340

City/State (required) Frankfort, KY

Purchase Order Number: 105537

Turn Around Times:

1 - Day  2 - Day  3 - Day

Same Day (Must Call Ahead)

Weekend (Must Call Ahead)

*If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

No.	Client Sample ID	Date Collected	ASBESTOS						AIR			COMMENTS		
			PLM Pktn Count 400	PLM Pktn Count 1000	PLM by Protocol	PCM	TEM Grids (Bulb)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (L/min)		Total Time (min)	Volume (Total Liters)
1	CT-Mez-8	2/25/12												3x3 Deep Ceiling Tile
2	CT-Mez-9													" " "
3	CT-Mez-10													" " "
4	CT-Mez-11													" " "
5	CT-Mez-12													12" Floor Tile (Center Room) w/ Blue
6	CT-Mez-13													" " "
7	CT-Mez-14													" " "
8	CT-Mez-15													2x4 Deep Ceiling Tile
9	CT-Mez-16													" " "
10														" " "

Sample Fill Positive  
Sample Fill Positive  
Sample Fill Positive

Signature: [Signature]

Signature: [Signature]

Date/Time: 3/12/12



**EHS**  
Laboratories

Environmental Hazards Services, LLC  
www.leadlab.com 7469 Whitepine Rd  
(800)347-4010 Richmond, VA  
(804)275-4907 (fax) 23237

# Asbestos Chain-of-Custody

~ For Lab Use Only ~

Company Name: Air Source Technology Inc. Address: 160 Prosperous Pl. Ste. 201,  
City/State/Zip: Lexington, KY 40509  
Phone: (859)299-0046 Fax: 859-299-0494 E  
Project Name/Testing Address: 7530; Commonwealth of KY (Capitol Tower) E-mail: support@airsourcetechnology.com  
City/State (required): Ky Acct. Number: 18-4340  
Collected by: ChA Certification Number: \_\_\_\_\_ Purchase Order Number: 105937

Turn Around Times: 3 - Day  Same Day (Must Call Ahead)  Weekend (Must Call Ahead)

*If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.*

No.	Client Sample ID	Date Collected	ASBESTOS						AIR			COMMENTS						
			PLM Count 1000	PLM Count 40	PLM % Protocol	TEM Count (Bald)	TEM Count (Air)	Time On	Time Off	Flow Rate (L/min)	Tral Time (minutes)		Volume (Total Liters)					
1	CF-Ground-1	2/29/12 X																
2	CF-Ground-2																	
3	CF-Ground-3																	
4	CF-Ground-4																	
5	CF-Ground-5																	
6	CF-Ground-6																	
7	CF-																	
8	CF-																	
9	CF-																	
10	CF-																	

Sample #1 Positive  
Sample #2 Still positive

Released by: Chris Jenkins Signature: \_\_\_\_\_ Date/Time: 3/1/12  
Received by: R TYLEN Signature: \_\_\_\_\_



# Asbestos Bulk Analysis Report

Environmental Hazards Services, L.L.C.  
7469 Whitepine Rd  
Richmond, VA 23237

Telephone: 800.347.4010

Report Number: 12-02-01410

Client: Air Source Technology Inc.  
160 Prosperous Pl. Ste. 201  
Lexington, KY 40509

Received Date: 02/10/2012  
Analyzed Date: 02/10/2012  
Reported Date: 02/10/2012

Project/Test Address: C7530, Comm of KY: Capital Tower; Frankfort, KY

Client Number:  
18-4340

Fax Number:  
859-299-0494

## Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-02-01410-001	CT-1		White Powdery; Fibrous	8% Chrysotile 12% Amosite	5% Fibrous Glass 75% Non-Fibrous
				Total Asbestos: 20%	
12-02-01410-002A	CT-2	Tile	White/Gray Vinyl	2% Chrysotile	98% Non-Fibrous
				Total Asbestos: 2%	
12-02-01410-002B	CT-2	Mastic	Black Adhesive	5% Chrysotile	95% Non-Fibrous
				Total Asbestos: 5%	
12-02-01410-003	CT-3		Off-White Fibrous; Silver Foil	NAD	5% Cellulose 75% Fibrous Glass 20% Non-Fibrous
12-02-01410-004	CT-4		Gray/White Cementitious	NAD	100% Non-Fibrous
12-02-01410-005	CT-5		White Powdery; Fibrous	8% Chrysotile 2% Amosite	15% Fibrous Glass 75% Non-Fibrous
				Total Asbestos: 10%	

## Environmental Hazards Services, L.L.C

Client Number: 18-4340  
 Project/Test Address: C7530, Comm of KY: Capital Tower;  
 Frankfort, KY

Report Number: 12-02-01410

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-02-01410-006	CT-6		Light Gray Powdery; Fibrous	NAD	5% Cellulose 25% Fibrous Glass 70% Non-Fibrous
12-02-01410-007A	CT-7	Tile	White/Gray Vinyl	4% Chrysotile	96% Non-Fibrous
				Total Asbestos: 4%	
12-02-01410-007B	CT-7	Mastic	Black Adhesive	3% Chrysotile	97% Non-Fibrous
				Total Asbestos: 3%	
12-02-01410-008	CT-8		White/Tan Fibrous; Silver Foil	NAD	15% Cellulose 65% Fibrous Glass 20% Non-Fibrous
12-02-01410-009	CT-9		Light Gray Cementitious; Granular	NAD	100% Non-Fibrous

## Environmental Hazards Services, L.L.C

Client Number: 18-4340  
Project/Test Address: C7530, Comm of KY: Capital Tower;  
Frankfort, KY

Report Number: 12-02-01410

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
-------------------	----------------------	------------	-----------------------	----------	-----------------

QC Sample: 7-M1-1991-3  
QC Blank: SRM 1866 Fiberglass  
Reporting Limit: 1% Asbestos  
Method: EPA Method 600/R-93/116  
Analyst: Katherine Charles Harris

Reviewed By Authorized Signatory:



Tasha Eaddy  
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

\* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

---

LEGEND: NAD = no asbestos detected

---



Environmental Hazards Services, LLC  
 www.leadlab.com 7469 Whitepine Rd  
 (800)347-4010 Richmond, VA  
 (804)275-4907 (fax) 23237

# Asbestos Chain-of-Custody

12-02-01410



Due Date:  
 02/10/2012  
 (Friday)  
 AE

Y11

City/State/Zip: Lexington, KY 40509

Acct. Number: 18-4340

E-mail: expect@air-sourcetechnology.com

City/State(required) Frankfort, KY

Purchase Order Number: 105917

Address: 160 Prosperous Pl. Ste. 201,

Fax: 859-299-0494 E

E-mail: expect@air-sourcetechnology.com

City/State(required) Frankfort, KY

Certification Number: 7110112

Collected by: M. S. A. Sameday Rushous

Turn Around Times: If no TAT is specified, sample(s) will be processed and charged as 3-day TAT.

1 - Day  2 - Day  3 - Day  Same Day (Must Call Ahead) \_\_\_\_\_ Weekend (Must Call Ahead) \_\_\_\_\_

No.	Client Sample ID	Date Collected	ASBESTOS						AIR			Volume (Total Liters)	COMMENTS	
			PM10 (Coast 400)	PM10 (Coast 1000)	PM10 (N-Protocol)	PCM	TEM Certified (Bulk)	TEM AHERA (Air)	Time On	Time Off	Flow Rate (l/min)			Total Time (mins)
1	CF-1	2/7/12	X											Pipe Insulation
2	CF-2													12" Flat Pipe w/ Black Wash
3	CF-3													2x2 DCT
4	CF-4													Leaving Plaster
5	CF-5													App Grout
6	CF-6													Pipe Grout
7	CF-7													12" Flat Pipe w/ Black Wash
8	CF-8													2x2 DCT
9	CF-9													Leaving Plaster
10														
Released by: <u>Chris Atkins</u>		Signature: <u>[Signature]</u>		Date/Time: <u>2/8/12 9am</u>		Docket # <u>91A117</u>								
Received by: <u>mswiler</u>		Signature: <u>[Signature]</u>		Date/Time: <u>2/8/12 9am</u>		Docket # <u>91A117</u>								



# Asbestos 400 Point Count Analysis Report

Environmental Hazards Services, L.L.C.  
7469 Whitepine Rd  
Richmond, VA 23237  
Telephone: 800.347.4010

Report Number: 12-03-01453

Client: Air Source Technology Inc.  
160 Prosperous Pl. Ste. 201  
Lexington, KY 40509

Received Date: 03/01/2012  
Analyzed Date: 03/13/2012  
Reported Date: 03/13/2012

Project/Test Address: C7530; Commonwealth of KY (Capital Tower); Frankfort,  
KY PO 105937; EHS# 12-03-00631

Client Number:  
18-4340

Fax Number:  
859-299-0494

## Laboratory Results

Lab Sample Number	Client Sample Number	Lab Gross Description	% Asbestos	Narrative ID
12-03-01453-001	CT-15-1 Tile	Gray Vinyl	0.75 % Chrysotile	
12-03-01453-002	CT-MEZ-4	White Textured, Fibrous	0.50 % Chrysotile	
12-03-01453-003	CT-MEZ-5	White Textured, Fibrous	0.25 % Chrysotile	
12-03-01453-004	CT-MEZ-6	White Textured, Fibrous	0.50 % Chrysotile	
12-03-01453-005	CT-MEZ-7 Tile	Tan Vinyl	1.00 % Chrysotile	
12-03-01453-006	CT-MEZ-11 Tile	White Vinyl	0.75 % Chrysotile	
12-03-01453-007	CT-MEZ-11 Mastic	Black Adhesive	1.25 % Chrysotile	

# Environmental Hazards Services, L.L.C

Client Number: 18-4340  
Project/Test Address: C7530; Commonwealth of KY (Capital Tower);  
Frankfort, KY PO 105937; EHS# 12-03-00631

Report Number: 12-03-01453

---

Lab Sample Number	Client Sample Number	Lab Gross Description	% Asbestos	Narrative ID
-------------------	----------------------	-----------------------	------------	--------------

---

Reporting Limit: 0.25 % Asbestos  
Method: EPA Method 600/R-93/116  
Analyst: Kathy Sizemore



Reviewed By Authorized Signatory: \_\_\_\_\_

Irma Faszewski  
QA/QC Manager


The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714.

---

LEGEND      NAD = No Asbestos Detected

---

**Appendix C**  
**Sample Locations**



Pipe Insulation/Joint Compound



Sample Locations



Pipe Joints/Linear Feet of Insulation



CT-Ground-1  
CT-Ground-2  
CT-Ground-3


GROUND FLOOR

**XX** Sample Locations

Pipe Insulation/Joint Compound

Floor Tile and Mastic

15  
Pipe Joints/Linear Feet of Insulation



MEZZANINE LEVEL

Pipe Insulation/Joint Compound


### Sample Locations

Pipe Joints/Linear Feet of Insulation



XX


60: Above Lobby Ceiling



Pipe Insulation/Joint Compound

XX Sample Locations

75 Pipe Joints/Linear Feet of Insulation




1st FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation



75




2nd FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation



75




3rd FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation



75




4th FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation



75




5th FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation




75



6th FLOOR

75  
Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation




7th FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation




75



8th FLOOR

 Pipe Insulation/Joint Compound  
 75  
 Pipe Joints/Linear Feet of Insulation



9th FLOOR




Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation



75




11th FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation



75




12th FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation

825



PLAN 13.A FLOOR SECTOR C-2 1/4" = 1'-0"

Pipe Insulation/Joint Compound




Sample Locations



Pipe Joints/Linear Feet of Insulation

25



PLAN 13-B FLOOR SECTOR C-2 1/8" = 1'-0"

Sample Locations




Pipe Insulation/Joint Compound



Floor Tile and Mastic



Pipe Joints/Linear Feet of Insulation



14th FLOOR


# Sample Locations



Pipe Insulation/Joint Compound



Pipe Joints/Linear Feet of Insulation




15th FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation

55




16th FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation

55




17th FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation

55




18th FLOOR

Pipe Insulation/Joint Compound

Pipe Joints/Linear Feet of Insulation


55



19th FLOOR

Pipe Insulation/Joint Compound


55 Pipe Joints/Linear Feet of Insulation



20th FLOOR

Pipe Insulation/Joint Compound


55  
Pipe Joints/Linear Feet of Insulation



21st FLOOR

Pipe Insulation/Joint Compound

55  
Pipe Joints/Linear Feet of Insulation



22nd FLOOR


# Sample Locations

XX

Pipe Insulation/Joint Compound

55

Pipe Joints/Linear Feet of Insulation



23rd FLOOR

Sample Locations




Pipe Insulation/Joint Compound




Pipe Joints/Linear Feet of Insulation

55



24th FLOOR



PLAN PENTHOUSE AND ROOF SECTOR C-2 1/8" = 1'-0"

